



Bact.#	Location	Date Sampled	Field Notes	ID #	Total Coliforms DC	E. coli DC	Background Growth DC	Alk Total	Barium	Cadmium	Calcium	Chloride	Chromium	Copper	Iron, Diss	Iron, Ext	Lead	Magnesium	Manganese	Nickel	Nitrate-N	pH (chem lab)	Phosphorus	Potassium	Sodium	Sulfate	Zinc
83	Tim Hortons Reads Corner	Apr 11, 2006	proportional @ well field.	178976	0	0	0														5.6						
84	S#7 Well Gallant St.	Apr 11, 2006	#9. Chlorine Residual - 0.24. @ Well head tap.	178977	0	0	0																				
85	S#1 Well Northmarket St.	Apr 11, 2006	#10. Chlorine Residual - 0.27. Sample @ hose on well head tap.	178978	0	0	0																				
86	Wilmot Well Field #W3 & W#5 Well	Apr 11, 2006	Wilmot down for residual for 15 min.	178979	0	0	0																				
87	St. Eleanors well # SE1	Apr 11, 2006	#12. Residual - 0.22. @ well head tap.	178980	0	0	0																				
88	St. Eleanors Community Center	Apr 25, 2006	(902) 436-5376.	179418	0	0	0																				
89	Impact Auto glass	Apr 25, 2006	(902) 436-5376.	179419	0	0	0																				
90	Baken Doughnuts	Apr 25, 2006	436-5376.	179420	0	0	0																				
91	Lions club Seniors residence	Apr 25, 2006	436-5376.	179421	0	0	0																				
92	Summerside Fire Hall	Apr 25, 2006	(902) 436-5376.	179422	0	0	0																				
93	Summerside Town Garage	Apr 25, 2006	night. PLEASE FAX COPY OF RESULTS TO (902) 436-5376.	179423	0	0	0																				
94	Novus Auto Glass	Apr 25, 2006	RESULTS TO (902) 436-5376.	179424	0	0	0																				
95	tim Hortons Reads corner	Apr 25, 2006	RESULTS TO (902) 436-5376.	179425	0	0	0															7.9					
96	S#7 Well Gallant St.	Apr 25, 2006	436-5376.	179426	0	0	0															7.9					
97	S#1 Well Northmarket St.	Apr 25, 2006	TO (902) 436-5376.	179427	0	0	0																				
98	Wilmot Well Field #W1 Well	Apr 25, 2006	Bldg. PLEASE FAX COPY OF RESULTS TO (902) 436-5376.	179428	0	0	0																				
99	St. Eleanors well # SE1	Apr 25, 2006	(902) 436-5376.	179429	0	0	0																				
100	St. Eleanors Irving	May 9, 2006	1. Chlorine - 0.11. Sample @	180135	0	0	0																				
101	Hickens garage	May 9, 2006	2. Chlorine - 0.08. Tap in garage set tub.	180136	0	0	0																				
102	PC Hospital	May 9, 2006	3. Chlorine. Sample @ 0.09.	180137	0	0	0															4.2					
103	notre Dame Take-out	May 9, 2006	4. Chlorine - . Tap in washroom - .	180138	0	0	0																				
104	Three Oaks High School	May 9, 2006	5. Mechinal Room Tap. Chlorine - 0.09.	180139	0	0	0															9.8					
105	24 hour Irving	May 9, 2006	6. Chlorine - 0.08. Display Counter Tap.	180140	0	0	0																				
106	Century 21	May 9, 2006	7. Chlorine - 0.07. Taken @ Lunch Room Tap.	180141	0	0	0																				
107	Cairns Motel	May 9, 2006	8. Chlorine - 0.14. Tap in office closet.	180142	0	0	0																				
108	S#7 Well Gallant St.	May 9, 2006	9. Chlorine - 0.19. @ Well Head Tap..	180143	0	0	0																				
109	S#1 Well Northmarket St.	May 9, 2006	10. Chlorine - 0.14. Sample @.	180144	0	0	0																				
110	Wilmot Well Field #W5 Well	May 9, 2006	11. Chlorine - 0.19. Sample in pipe gallery @ chlorine building.	180145	0	0	0															9.8					
111	St. Eleanors well # SE1	May 9, 2006	12. Chlorine - 0.22. Tap @ well head hose..	180146	0	0	0																				
112	Sharkies restaurant	May 12, 2006	CALL 439-5322 WITH RESULTS, GARY MCINNIS.	180451	0	0	0																				
113	old Wing Building	May 12, 2006	CALL 439-5322 WITH RESULTS, GARY MCINNIS.	180452	0	0	0																				
114	S#10 greenwood Drive	May 15, 2006	S-4864.	180546	1	0	1																				
115	S#10 greenwood Drive	May 16, 2006	sample are clear.	180658	0	0	0																				
116	St. Eleanors well # SE1	May 23, 2006	1. Chlorine Residual .14. Kitchen sink.	180972	0	0	0																				
117	Baken Doughnuts Granville St.	May 23, 2006	3. Chlorine Residual .018. Kitchen sink.	180974	0	0	0																				
118	Elm St. School	May 23, 2006	4. Chlorine Residual .010. Sample taken @ Janitors Store Room Sink.	180975	0	0	0																				
119	western School div. Bus Depot	May 23, 2006	5. Maintenance Garage. Chlorine Residual .011. Sample taken @ lunchroom tap.	180976	0	0	0															9.3					
120	Summer Side Fire Hall	May 23, 2006	6. Chlorine Residual .09. Sample @ Mechi Room Sink.	180977	0	0	0																				
121	MacArthur's Petro can	May 23, 2006	7. Chlorine Residual .09. Sample @ Mens Washroom Sink.	180978	0	0	0																				
122	Tim Horton's reads Corner	May 23, 2006	8. Chlorine Residual - .	180979	0	0	0																				
123	S#7 Well Gallant St.	May 23, 2006	9. Chlorine Residual .023. Sample @ Well Head Tap.	180980	0	0	0															10.2					
124	S#1 Well Northmarket St.	May 23, 2006	10. Chlorine Residual .026.	180981	0	0	0																				
125	Wilmot Well Field #W5 Well	May 23, 2006	11. Chlorine Residual .017. @ Well Pipe Gallery Chlorine Building.	180982	0	0	0															10.2					
126	St. Eleanors well # SE4	May 23, 2006	12. Chlorine Residual .014. Hose from Well Head Tap.	180983	0	0	0																				
127	well #10 greenwood	May 23, 2006	13. Chlorine Residual .018. Hose from Well Head Tap.	180984	0	0	0																				
128	bernars quickMart	Jun 5, 2006	1. Chlorine @ 0.15. Sample @ Laundry Tub in Laundromat.	181873	0	0	0																				
129	Pope Road Variety	Jun 5, 2006	2. Chlorine @ 0.18. Sample @ Coffee Counter Sink.	181874	0	0	0																				
130	Baken duogunuts	Jun 5, 2006	3. Chlorine @ 0.11. Sample @ Kitchen Counter.	181875	0	0	0																				
131	Lions Club seniors Residence	Jun 5, 2006	4. Chlorine @ 0.11. Sample Common Room Sink.	181876	0	0	0																				
132	Three Oaks School	Jun 5, 2006	7. Chlorine @ 0.11. Sample @ Basement Mens Washroom.	181877	0	0	0																				
133	City Hall	Jun 5, 2006	8. Chlorine @ 0.12. Sample in Tims Bakery Station..	181878	0	0	0	105.8	0.338	0	61.9	21.5	0	0.033		0	0	1.37	0	0	7	7.7	0	0.721	7.91	14.5	0
134	Wilmot community center	Jun 5, 2006	9. Chlorine @ 0.08. Sample @ Well Head Tap.	181879	0	0	5																				
135	tim hortons summerside	Jun 5, 2006	10. Chlorine @ 0.21. Sample @ Hose From Well Head Tap.	181880	0	0	0																				
136	S#7 Well Gallant St.	Jun 5, 2006	11. Chlorine @ 0.14. Sample @ Chlorine Building Pipe Gallery.	181881	0	0	0																				
137	S#1 Well Northmarket St.	Jun 5, 2006	12. Chlorine @ 0.22. Sample @ Hose From Well Head Tap.	181882	0	0	0																				
138	Wilmot Well Field #W1 Well & w5	Jun 5, 2006	13. Chlorine @ 0.16. Sample @ Hose From Well Head Tap.	181883	0	0	0																				
139	St. Eleanors well # SE4	Jun 5, 2006	5. Chlorine @ 0.18. Sample In Mechanical Room Sink.	181884	0	0	0	110.9	0.369	0	59.6	17.2	0	0		0	0	1.39	0	0	5.4	7.7	0	0.688	7.56	14.5	0
140	well #10 greenwood	Jun 5, 2006	6. Chlorine @ 0.09. Sample @ Lunchroom Sink In Basement. NITRATES ONLY.	181885	0	0	0	164.5	0.863	0	114	123.6	0	0.112		0	0	3.59	0	0	2.9	7.7	0	1.43	38.2	17.7	0
141	givrn to Trevor	Jun 5, 2006	15. - Trevors Home Well - Not On City System.	181886																							
142	not tested wrong bottle	Jun 20, 2006	Request Form. #14 on Bottle)..	183124																	10.4						
143	Waites Electric	Jun 20, 2006																									



Bact.#	Location	Date Sampled	Field Notes	ID #	Total Coliforms DC	E. coli DC	Background Growth DC	Alk Total	Barium	Cadmium	Calcium	Chloride	Chromium	Copper	Iron, Diss	Iron, Ext	Lead	Magnesium	Manganese	Nickel	Nitrate-N	pH (chem lab)	Phosphorus	Potassium	Sodium	Sulfate	Zinc	
239	Needs Convenience Store	Sep 26, 2006	Property ID No.: #5. Sample Taken At: Sink in Back Room. Chlorine Residual: .09.	191031	0	0	0																					
240	Wedgewood Manor	Sep 26, 2006	Property ID No.: #4. Sample Taken At: Boiler Room Sink. Chlorine Residual: .10.	191032	0	0	0																					
241	Granville St. Gas Bar	Sep 26, 2006	Property ID No.: #3. Sample Taken At: Sink in Kitchen. Chlorine Residual: .10.	191033	0	0	0																					
242	Pope Rd Variety	Sep 26, 2006	Property ID No.: #2. Sample Taken At: Sink. Chlorine Residual: .12.	191034	0	0	0																					
243	St. Eleanors Community center	Sep 26, 2006	Property ID No.: #1. Sample Taken At: Sink in Kitchen. Chlorine Residual: .11.	191035	0	0	0																					
244	89 Harvard St.	Oct 5, 2006	service line for Harvard job.	191595	3	0	180																					
245	B&R Storage	Oct 5, 2006	S-6227. #2. Chlorine Residual - 0.01. Sample from inside building in bathroom.	191596	30	0	200																					
246	St. Eleanors Community center	Oct 10, 2006	Sink.	191699	0	0	0																					
247	Waites Electric	Oct 10, 2006	Sink.	191700	0	0	0																					
248	MacAruther's Esso	Oct 10, 2006	Property ID No: 3. Chlorine Residual @ 0.15. Sample @ Lunch Counter Sink.	191701	0	0	0																					
249	Notre Dame Take -out	Oct 10, 2006	Property ID No: 4. Chlorine Residual @ Sample @ Kitchen Sink.	191702	0	0	0																					
250	Three Oaks High School	Oct 10, 2006	Property ID No: 5. Chlorine @ 0.11. Sample @ Mechanical Room Sink.	191703	0	0	0	102.9	0.398	0	65.9	27.2	0	0.027	0	0	1.37	0	0	6.8	7.7	0.04	0.698	8.41	15.4	0		
251	412 North Market St.	Oct 10, 2006	Property ID No: 6. Chlorine Residual 0.09. Sample @ Hose Bib Tap.	191704	0	0	0																					
252	Ben's Bakery	Oct 10, 2006	Property ID No: 7. Chlorine Residual @ 0.09. Sample @ Bathroom Taps.	191705	0	0	0	104.2	0.392	0	63.1	25.1	0	0.55	0	0	1.29	0	0	6.1	7.7	0.029	0.704	7.76	14.8	0		
253	Reads Corner Esso	Oct 10, 2006	Property ID No: 8. Chlorine Residual @ 0.08. Sample @ Bakery Sink.	191706	0	0	0																					
254	S#7 Well Gallant St.	Oct 10, 2006	Property ID No: 9. Chlorine Residual @ 0.19. Sample @ Well Head Tap.	191707	0	0	0																					
255	S#1 Well Northmarket St.	Oct 10, 2006	Property ID No: 10. Chlorine Residual. Sample From Hose From Well Head Tap..	191708	0	0	0																					
256	Wilmot Well Field #W1 Well	Oct 10, 2006	In Chlorine Building.	191709	1	0	0																					
257	St. Eleanors well # SE1	Oct 10, 2006	Property ID No: 12. Chlorine Residual @ 0.26. Sample @ Tap From Well Head.	191710	0	0	0																					
258	89 Harvard St.	Oct 11, 2006	Harvard St. main replacement. Chloride Residual 0.19. Sample @ hose to -	191838	80	0	200																					
259	77 Harvard St.	Oct 11, 2006	Harvard St. from temp line on north side of Harvard St.	191839	2	0	1																					
260	89 Harvard St.	Oct 16, 2006	Residual @ 5 min. flush 0.11.	192016	7	0																						
261	77 Harvard St.	Oct 16, 2006	Residual @ 0.05 @ 5 min. flush.	192017	2	0	0																					
262	15 Johnston St.	Oct 16, 2006	#3. Residual @ 0.19. Sample @ kitchen tap. - 5 min. flush.	192018	80	0	200																					
263	89 Harvard St.	Oct 17, 2006	system on South Side. 6 m flush Residual @.	192090	0	0	2																					
264	77 Harvard St.	Oct 17, 2006	hose to tem water system. Residual @.	192091	0	0	1																					
265	11 Johnston St.	Oct 17, 2006	#3. Residual @ 0.16. Sample at Kitchen Sink.	192092	0	0	0																					
266	Town garage	Oct 18, 2006	#1. Residual - 0.10. Sample @ Lunch Room Sink. 5 - Min Flush.	192164	0	0	0																					
267	89 Harvard St.	Oct 18, 2006	10.0 min. flush R - 0.40. On the South Side of Harvard Temp. System.	192165	6	0	11																					
268	72 Harvard St.	Oct 18, 2006	North Side of Harvard Temp. Water System.	192166	0	0	0																					
269	19 Johnston St.	Oct 18, 2006	#4. Sample @ Outside Hose Bib Tap. Residual @ 0.29.	192167	0	0	0																					
270	Electric Plant	Oct 18, 2006	Sample @ Lunch Room Sink. Residual 0.4.	192168	0	0	0																					
271	89 Harvard St.	Oct 20, 2006	inside build B & R Storage.	192284	8	0	2																					
272	well #10 Greenwood	Oct 20, 2006	S-6324. #10.	192298	0	0	0																					
273	89 Harvard St.	Oct 23, 2006	1 min flush. Sample @ hose bib.	192319	0	0	13																					
274	1 West Dr.	Oct 24, 2006	#1. Residual @ 0.28. Sample @ lunchroom sink.	192395	0	0	0																					
275	hickens Garage	Oct 24, 2006	#2. Residual @ 0.17. Sample @ work bay sink.	192396	0	0	0																					
276	Granville St. Gas Bar	Oct 24, 2006	#3. Residual @ 0.26. Sample @ doughnut counter sink.	192397	0	0	0																					
277	Needs Convenience Store	Oct 24, 2006	#4. Residual @ 0.10. Sample @ mechanical room sink.	192398	0	0	0																					
278	western school board Bud Depot	Oct 24, 2006	#5. Maintenance Shop. Residual @ 0.17. Sample @ lunch room sink.	192399	0	0	0																					
279	summerside Fire Hall	Oct 24, 2006	#6 (Six). Residual @ 0.29. Sample @ mechanical room sink.	192400	0	0	0																					
280	155 Gillespie Ave	Oct 24, 2006	#7. Residual @ 0.39. Sample @ outside hose bib.	192401	45	0	30																					
281	Tim's Read 's Corner	Oct 24, 2006	#8. Residual @ 0.31. Sample at bakery sink.	192402	0	0	0																					
282	S#7 Well Gallant St.	Oct 24, 2006	#9. Residual @ 0.30. Sample @ well head tap.	192403	0	0	0																					
283	S#1 Well Northmarket St.	Oct 24, 2006	#10. Residual @ 0.19. Sample @ hose from well head tap.	192404	0	0	0																					
284	Wilmot Well Field #W3 Well	Oct 24, 2006	#11. Residual @ 0.32. Sample @ tap from pipe gallery @ chlorine building.	192405	0	0	0																					
285	St. Eleanors well # SE1	Oct 24, 2006	#12. Residual @ 0.33. Sample @ well head tap.	192406	0	0	0																					
286	well #10 Greenwood	Oct 24, 2006	outside B & R Storage.	192408	0	0	0																					
287	89 Harvard St.	Oct 24, 2006	hose bib.	192409	0	0	0																					
288	155 Gillespie Ave	Oct 26, 2006	Flushed Gillespie for 45 min.	192585	0	0	1																					
289	77 Harvard St.	Nov 2, 2006	Harvard St. Chlorine Residual .19	192931	0	0	0																					
290	B& R Rentals	Nov 2, 2006	side of Harvard St. Chlorine Residual .14	192932	10	0	2																					
291	St. Eleanors Community center	Nov 7, 2006	Station ID: 1. Residual @ 0.13. Sample @ Lunch Room Sink.	193059	0	0	0																					
292	Bernards Quickmart	Nov 7, 2006	Station ID: 2. Residual @ 0.27. Sample @ Laundry Mat Set Tub.	193060	0	0	0																					
293	hickens Garage	Nov 7, 2006	Station ID: 3. Residual @ 0.17. Sample @ Bakin Donuts Counter.	193061	0	0	0																					
294	Pope Road Variety	Nov 7, 2006	Station ID: 4. Residual @ 0.10. Sample @ Common Room Sink.	193062	0	0	0																					
295	Athena High school	Nov 7, 2006	Station ID: 5. Residual @ 0.15. Sample @ Staff Lounge Sink.	193063	0	0	0																					
296	Summerside City Hall	Nov 7, 2006	Station ID: 6. Residual @ 0.21. Sample @ Lunch Room Sink.	193064	0	0	0																					
297	Three Oaks High School	Nov 7, 2006	Station ID: 7. Residual @ 0.18. Sample @ Wash Room Sink.	193065	0	0	0																					
298	155 Gillespie Ave	Nov 7, 2006	Bakery Sink.	193066	0	0	0																					
299	S#7 Well Gallant St.	Nov 7, 2006	Station ID: 9. Residual @ 0.13. Sample @ Well Head Tap.	193067	0	0	0																					
300	S#1 Well Northmarket St.	Nov 7, 2006	Station ID: 10. Residual @ 0.26. Sample @ Hose from Well Head Tap.	193068	0	0	0																					
301	Wilmot Well Field #W1 Well	Nov 7, 2006	Chlorine Bldg. Pipe Gallery Tap.	193069	0	0	0																					
302	St. Eleanors well # SE1	Nov 7, 2006	Station ID: 12. Residual @ 0.22. Sample @ Well Head Tap.	193070	0	0	0																					
302	well # 10 Greenwood	Nov 16, 2006	Well sample to be put back into service after new pump installed. No chlorine	193574	80	1	0																					
303	well # 10 Greenwood	Nov 20, 2006	S-6479. #10. Sample taken at well head.	193666	3	0	10																					
304	St. Eleanors Community center	Nov 21, 2006	1. Residual - 0.18. Sample @ kitchen sink.	193699	0	0	0																					
305	Bernards Quickmart	Nov 21, 2006	2. Residual - @ 0.18. Sample @ laundry set tub.	193700	0	0	0																					
306	hickens Garage	Nov 21, 2006	3. Residual @ 0.17. Sample @ Baken Dougnuts counter sink.	193701	0	0	0																					
307	Granville St. Gas Bar	Nov 21, 2006	4. Residual @ 0.12. Sample @ Mechanical room sink.	193702	0</																							

